ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone	Ward No.	Ward Name
YELAHANKA	5	Jakkuru
Street ID	**Street Name**	**Significant Landmark**
W1000, W0992, W0994, W1727	NA, 5th Main Rd	Jakkur Near Govt school
Segment No.	**Total Length (m)**	
5/C-W1000/S100504	92.65	

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	92.65	77.607392	13.076512	77.607609	13.077322	Jakkur Keni school	main road

Work Details

History of Road / Lane / Circles

Name of the Work	Sanctioned Estimated Amount (Rs.)	Sanctioned Year
Improvements to road and drains at Jakkur Extension in ward no. 05 Byatarayanapura sub division	3000000	2016-17
Year	**Type of Work**	**Other Work Type**
2016 - 2017	Others	RCC drain
Tender	**Work Details**	**Job No. / Work Code**
Tender	RCC drain	005-17-000016
Work Order No.	**Work Order Date**	**Period of Extention**
BBMP/EE/BTP/WO/99/2017-18	05/08/2017	
Defect Liability Period From	**Defect Liability Period To**	**Multiple road involved with the same Job No/ Work Code #**
15/09/2017	15/09/2018	No

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)
K.Narasimharaju		0.00
Phone No.	**E-Mail ID**	
9448083246		

Zone: YELAHANKA **Ward No:** 5 **Ward Name:** Jakkuru **Street ID:** W1000, W0992, W0994, W1727

ಸಹಾಯಕ ಅಭಿಯಂತರರು
ಬಿ.ಬಿ.ಎಂ.ಪಿ. ಬ್ಯಾಟರಾಯನಪುರ ಉಪ ವಿಭಾಗ

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ಬ್ಯಾಟರಾಯನಪುರ ಉಪ ವಿಭಾಗ
ಬಿ.ಬಿ.ಎಂ.ಪಿ., ಬೆಂಗಳೂರು-24

d Inspection Details

Number of Trees	Any Other Information	Name
0		chandrappa h
Date of Inspection	**Remarks**	
27/10/2017		

Category	Image	Photo Remark
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	Parameshwaraiah	27/10/2017	26/11/2017	Approved
SE	K.M.Vasu	27/10/2017	26/11/2017	Verify
EE	H.T.Mohandas	27/10/2017	26/11/2017	Verify
AEE	B.s. Sridhar	27/10/2017	26/11/2017	Verify
AE	Chandrappa H	27/10/2017	26/11/2017	Mobile verification is done
AE	Chandrappa H	27/10/2017	26/11/2017	Forwarded

Zone: YELAHANKA **Ward No:** 5 **Ward Name:** Jakkuru **Street ID:** W1000, W0992, W0994, W1727

ಸಹಾಯಕ ಅಭಿಯಂತರರು
ಬಿ.ಬಿ.ಎಂ.ಪಿ. ಬ್ಯಾಟರಾಯನಪುರ ಉಪ ವಿಭಾಗ

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ಬ್ಯಾಟರಾಯನಪುರ ಉಪ ವಿಭಾಗ
ಬಿ.ಬಿ.ಎಂ.ಪಿ. ಬೆಂಗಳೂರು-26

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone	Ward No.	Ward Name
YELAHANKA	5	Jakkuru
Street ID	**Street Name**	**Significant Landmark**
W0978	NA	near K.V. byregowa kalamandire
Segment No.	**Total Length (m)**	
5/S-W0978/S095520	77.32	

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	77.32	77.606643	13.078446	77.607326	13.078245	Jakkur govt school main road	Amruthahalli main road

Work Details

History of Road / Lane / Circles

Name of the Work	Sanctioned Estimated Amount (Rs.)	Sanctioned Year
Improvements to road and drains at Jakkur Extension in ward no. 05 Byatarayanapura sub division	3000000	2016-17
Year	**Type of Work**	**Other Work Type**
2016 - 2017	Others	RCC drain and covering slab
Tender	**Work Details**	**Job No. / Work Code**
Tender	RCC drain and covering slab	005-17-000016
Work Order No.	**Work Order Date**	**Period of Extention**
BBMP/EE/BTP/WO/99/2017-18	05/08/2017	
Defect Liability Period From	**Defect Liability Period To**	**Multiple road involved with the same Job No/ Work Code #**
15/09/2017	15/09/2018	No

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)
K.Narasimharaju		0.00
Phone No.	**E-Mail ID**	
9448083246		

ಸಹಾಯಕ ಅಭಿಯಂತರರು
ಬಿ.ಬಿ.ಎಂ.ಪಿ. ಬ್ಯಾಟರಾಯನಪುರ ಉಪ ವಿಭಾಗ

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ಬ್ಯಾಟರಾಯನಪುರ ಉಪ ವಿಭಾಗ
ಬಿ.ಬಿ.ಎಂ.ಪಿ., ಬೆಂಗಳೂರು-74

d Inspection Details

Number of Trees	Any Other Information	Name
0		chandrappa h
Date of Inspection	**Remarks**	
27/10/2017		

Category	Image	Photo Remark
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	Parameshwaraiah	27/10/2017	26/11/2017	Approved
SE	K.M.Vasu	27/10/2017	26/11/2017	Verify
EE	H.T.Mohandas	27/10/2017	26/11/2017	Verify
AEE	B.s. Sridhar	27/10/2017	26/11/2017	Verify
AE	Chandrappa H	27/10/2017	26/11/2017	Mobile verification is done
AE	Chandrappa H	27/10/2017	26/11/2017	Forwarded

ಸಹಾಯಕ ಅಭಿಯಂತರರು
ಬಿ.ಬಿ.ಎಂ.ಪಿ. ಬ್ಯಾಟರಾಯನಪುರ ಉಪ ವಿಭಾಗ

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ಬ್ಯಾಟರಾಯನಪುರ ಉಪ ವಿಭಾಗ
ಬಿ.ಬಿ.ಎಂ.ಪಿ, ಬೆಂಗಳೂರು-24